

Flamingo Crescent Playground BOQ					
Section	Material	Quantity	Cost/Unit	Actual Cost (Rand)	Notes
Paint	Mastercoat - White 5L	3	250	750	Optimum Hardware
	Tint, Blue 50mL	1	16.5	17	Optimum Hardware
	Tint, Green 50mL	1	16.5	17	Optimum Hardware
	Tint, Red 50mL	1	16.5	17	Optimum Hardware
	Tint, Yellow 50mL	1	16.5	17	Optimum Hardware
	Tint, Orange 50mL	2	11	22	BuildIt
	Tint, Green 50mL	1	11	11	BuildIt
	Tint, Red 50mL	2	11	22	BuildIt
	Tint, Yellow 50mL	2	11	22	BuildIt
	Tint, Magenta 50 mL	1	11	11	BuildIt
	Brush, 50mm	1	15	15	Optimum Hardware
	Brush, 100mm	3	24.5	74	Optimum Hardware
<i>(insert new rows above here)</i>					
<b>Paint Subtotal</b>				<b>993</b>	
Tire Structure	Masonry Bit 10mm	1	15	15	BuildIt
	Masonry Bit 12mm	1	32.5	33	Optimum Hardware
	Expansion Bolts 5x55 10pk	1	35	35	BuildIt
	Expansion Bolts 65x2A 2pk	1	27.5	28	Optimum Hardware
	Bolts 8x65mm Cup Square	20	2.95	59	BuildIt
	Bolts M8x65	50	2.5	125	Optimum Hardware
	Nuts 8M-10B 10pk	2	8.5	17	Optimum Hardware
	Nuts 8M-50B 50pk	1	27.5	28	Optimum Hardware
	Nuts 20pk	1	0.5	1	Optimum Hardware
	Gloss White 1L (Oil Paint)	1	50	50	BuildIt, discounted
	Tires	39	0	0	Arrow Tyres
<i>(insert new rows above here)</i>					
<b>Tire Structure Subtotal</b>				<b>389</b>	
Playstructure	Special 9	1	4800.00	4800	Playventures
	Slide	1	1350.00	1350	Playventures
<i>(insert new rows above here)</i>					
<b>Play Structure Subtotal</b>				<b>6150</b>	
Scenery	Trees	2	0	0	City Donation
	Stumps	8	0	0	City Donation
	Tires	8	0	0	Arrow Tyres, for seating
	Wood 38x114mm	1	0	0	Creche Extra
	<i>(insert new rows above here)</i>				
<b>Scenery Subtotal</b>				<b>0</b>	
<b>GRAND TOTAL</b>				<b>7532</b>	