

2021-TZES-026	Tappan Zee ES	1	Outside of Girls Bathroom by Room 205 Sink (left when facing) Faucet #1	6/4/2021	2.9	Not Required	Not Required	2.9	Yes	6/4/2021	Not Applicable
2021-TZES-027	Tappan Zee ES	1	Outside of Boys Bathroom by Room 204 Sink (left when facing) Faucet #1	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021-TZES-028	Tappan Zee ES	1	Outside of Boys Bathroom by Room 204 Sink (right when facing) Faucet #2	6/4/2021	1.4	Not Required	Not Required	1.4	Yes	6/4/2021	Not Applicable
2021-TZES-029	Tappan Zee ES	1	Classroom 205 Sink Faucet	6/4/2021	5.5	DO NOT DRINK signage installed; aerator changed; to be resampled	TBD	5.5	No	Pending	Not Applicable
2021-TZES-030	Tappan Zee ES	1	Classroom 205 Sink Fountain	6/4/2021	7.3	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021-TZES-031	Tappan Zee ES	1	Classroom 206 Sink Faucet	6/4/2021	1.7	Not Required	Not Required	1.7	Yes	6/4/2021	Not Applicable
2021-TZES-032	Tappan Zee ES	1	Classroom 207 Sink Faucet	6/4/2021	3.8	Not Required	Not Required	3.8	Yes	6/4/2021	Not Applicable
2021-TZES-033	Tappan Zee ES	1	Classroom 208 Sink Faucet	6/4/2021	2.5	Not Required	Not Required	2.5	Yes	6/4/2021	Not Applicable
2021-TZES-034	Tappan Zee ES	1	Classroom 209 Sink Faucet	6/4/2021	3.6	Not Required	Not Required	3.6	Yes	6/4/2021	Not Applicable
2021-TZES-035	Tappan Zee ES		Custodial Closet across from 209 Slop Sink	6/4/2021	4.6	Not Required	Not Required	4.6	Yes	6/4/2021	Not Applicable
2021-TZES-036	Tappan Zee ES	1	Hallway outside Classroom 217 Water Cooler Fountain	6/4/2021	<1.0	Even though this outlet is compliant; it will be permanently removed from serviced and replaced with new bottle filler water fountain.	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021-TZES-037	Tappan Zee ES	1	Outside of Girls Bathroom next to Room 217 Sink (left when facing) Faucet #1	6/4/2021	4.7	Not Required	Not Required	4.7	Yes	6/4/2021	Not Applicable
2021-TZES-038	Tappan Zee ES	1	Outside of Girls Bathroom next to Room 217 Sink (right when facing) Faucet #2	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021-TZES-039	Tappan Zee ES	1	Outside of Boys Bathroom next to Room 218 Sink (left when facing) Faucet #1	6/4/2021	1.8	Not Required	Not Required	1.8	Yes	6/4/2021	Not Applicable
2021-TZES-040	Tappan Zee ES	1	Outside of Boys Bathroom next to Room 218 Sink (right when facing) Faucet #2	6/4/2021	1.0	Not Required	Not Required	1.0	Yes	6/4/2021	Not Applicable
2021-TZES-041	Tappan Zee ES	1	Classroom 211 Sink Faucet	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021-TZES-042	Tappan Zee ES	1	Classroom 212 Sink Faucet	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021-TZES-043	Tappan Zee ES	1	Classroom 213 Sink Faucet	6/4/2021	2.3	Not Required	Not Required	2.3	Yes	6/4/2021	Not Applicable
2021-TZES-044	Tappan Zee ES	1	Classroom 214 Sink Faucet	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021-TZES-045	Tappan Zee ES	1	Classroom 215 Sink Faucet	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021-TZES-046	Tappan Zee ES	1	Classroom 216 Sink Faucet	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021-TZES-047	Tappan Zee ES	1	Classroom 302 Sink Faucet	6/4/2021	1.7	Not Required	Not Required	1.7	Yes	6/4/2021	Not Applicable
2021-TZES-048	Tappan Zee ES	1	Classroom 302 Sink Fountain	6/4/2021	3.1	Not Required	Not Required	3.1	Yes	6/4/2021	Not Applicable
2021-TZES-049	Tappan Zee ES	1	Hallway Outside Room 302 Bubbler Water Fountain	6/4/2021	9.6	Outlet permanently shut down; fountain to be replaced then resampled.	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable
2021-TZES-050	Tappan Zee ES		Across From Room 303 Custodial Closet Slop Sink	6/4/2021	13.8	DO NOT DRINK signage installed; classified as exempt under BOCES guidelines	Not Required	Not Applicable	Not Applicable	6/4/2021	Not Applicable
2021-TZES-051	Tappan Zee ES	1	Classroom 303 Sink Faucet	6/4/2021	5.3	DO NOT DRINK signage installed; aerator changed; to be resampled	TBD	Pending	No	Pending	Not Applicable

2021- TZES- 052	Tappan Zee ES	1	Classroom 303 Sink Fountain	6/4/2021	4.6	Not Required	Not Required	4.6	Yes	6/4/2021	Not Applicable
2021- TZES- 053	Tappan Zee ES	1	Classroom 304 Sink Faucet	6/4/2021	7.6	DO NOT DRINK signage installed; aerator changed; to be resampled	TBD	Pending	No	Pending	Not Applicable
2021- TZES- 054	Tappan Zee ES	1	Classroom 304 Sink Fountain	6/4/2021	21.4	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Not Applicable
2021- TZES- 055	Tappan Zee ES	1	Classroom 305 Sink Faucet	6/4/2021	12.3	DO NOT DRINK signage installed; aerator changed; to be resampled	TBD	Pending	No	Pending	Not Applicable
2021- TZES- 056	Tappan Zee ES	1	Classroom 305 Sink Fountain	6/4/2021	8.8	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Not Applicable
2021- TZES- 057	Tappan Zee ES	1	Classroom 306 Sink Faucet	6/4/2021	4.2	Not Required	Not Required	4.2	Yes	6/4/2021	Not Applicable
2021- TZES- 058	Tappan Zee ES	1	Hallway Outside Room 305 -Water Cooler Fountain (Combo Unit)- Mouth	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021- TZES- 059	Tappan Zee ES	1	Hallway Outside Room 305 -Water Cooler Fountain (Combo Unit)- Bottle Filler	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021- TZES- 060	Tappan Zee ES	1	Classroom 306 Bathroom Sink Faucet	6/4/2021	44.9	Outlet temporarily shut down; aerator replaced; to be resampled.	Pending	Pending	No	Pending	Not Applicable
2021- TZES- 061	Tappan Zee ES	1	Classroom 307 Classroom Sink Faucet	6/4/2021	6.2	DO NOT DRINK signage installed; aerator changed ; to be resampled	TBD	Pending	No	Pending	Not Applicable
2021- TZES- 062	Tappan Zee ES	1	Classroom 307 Bathroom Sink Faucet	6/4/2021	4.0	Not Required	Not Required	4.0	Yes	6/4/2021	Not Applicable
2021- TZES- 063	Tappan Zee ES	1	Classroom 308 Sink Faucet	6/4/2021	18.0	Outlet temporarily shut down; aerator replaced; to be resampled.	TBD	Pending	No	Pending	Not Applicable
2021- TZES- 064	Tappan Zee ES	1	Classroom 308 Sink Fountain	6/4/2021	1.1	Not Required	Not Required	1.1	Yes	6/4/2021	Not Applicable
2021- TZES- 065	Tappan Zee ES	1	Classroom 308 Bathroom Sink Faucet	6/4/2021	4.5	Not Required	Not Required	4.5	Yes	6/4/2021	Not Applicable
2021- TZES- 066	Tappan Zee ES	1	Classroom 309 Sink Faucet	6/4/2021	11.9	DO NOT DRINK signage installed; aerator changed; to be resampled	TBD	Pending	No	Pending	Not Applicable
2021- TZES- 067	Tappan Zee ES	1	Classroom 309 Sink Fountain	6/4/2021	8.5	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021- TZES- 068	Tappan Zee ES	1	Classroom 309 Bathroom Sink Faucet	6/4/2021	9.5	DO NOT DRINK signage installed; aerator changed; to be resampled	TBD	Pending	No	Pending	Not Applicable
2021- TZES- 069	Tappan Zee ES	1	Classroom 310 Faucet	6/4/2021	4.5	Not Required	Not Required	4.5	Yes	6/4/2021	Not Applicable
2021- TZES- 070	Tappan Zee ES	1	Classroom 310 Fountain	6/4/2021	5.6	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021- TZES- 071	Tappan Zee ES	1	Classroom 311 Faucet	6/4/2021	7.2	DO NOT DRINK signage installed; aerator changed; to be resampled	Not Required	Pending	No	Pending	Not Applicable
2021- TZES- 072	Tappan Zee ES	1	Classroom 311 Fountain	6/4/2021	3.9	Not Required	Not Required	3.9	Yes	6/4/2021	Not Applicable
2021- TZES- 073	Tappan Zee ES	1	Classroom 311 Bathroom Sink Faucet	6/4/2021	5.7	Exempt from further Testing - bathrooms not required to be sampled under new regulations	Not Required	Not applicable	Yes	1/1/2023	Not Applicable
2021- TZES- 074	Tappan Zee ES	1	Classroom 313 Faucet	6/4/2021	35.6	Outlet temporarily shut down; aerator replaced; to be resampled.	TBD	Pending	No	Pending	Not Applicable
2021- TZES- 075	Tappan Zee ES	1	Classroom 314 Faucet	6/4/2021	4.6	Not Required	Not Required	4.6	Yes	6/4/2021	Not Applicable
2021- TZES- 076	Tappan Zee ES	1	Outside of Girls Bathroom next to Room 314 Sink (left when facing) Faucet #1	6/4/2021	6.1	DO NOT DRINK signage installed; aerator changed; to be resampled	TBD	6.1	No	6/4/2021	Not Applicable
2021- TZES- 077	Tappan Zee ES	1	Outside of Girls Bathroom next to Room 314 Sink (right when facing) Faucet #2	6/4/2021	1.9	Not Required	Not Required	1.9	Yes	6/4/2021	Not Applicable
2021- TZES- 078	Tappan Zee ES	1	Outside of Boys Bathroom next to Room 314 Sink (left when facing) Faucet #1	6/4/2021	1.3	Not Required	Not Required	1.3	Yes	6/4/2021	Not Applicable
2021- TZES- 079	Tappan Zee ES	1	Outside of Boys Bathroom next to Room 314 Sink (right when facing) Faucet #2	6/4/2021	3.0	Not Required	Not Required	3	Yes	6/4/2021	Not Applicable
2021- TZES- 080	Tappan Zee ES	1	Classroom 401 (BOCES Guidance Office) Sink Faucet	6/4/2021	8.0	DO NOT DRINK signage installed; aerator changed; to be resampled	TBD	Pending	No	Pending	Not Applicable

2021- TZES- 081	Tappan Zee ES	1	Classroom 401 (BOCES Guidance Office) Sink Fountain	6/4/2021	2.7	Not Required	Not Required	2.7	Yes	6/4/2021	Not Applicable
2021- TZES- 082	Tappan Zee ES	1	Classroom 401 (BOCES Guidance Office) Bathroom Sink Fountain	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable
2021- TZES- 083	Tappan Zee ES	1	Classroom 402 (BOCES Main Office) Sink Faucet	6/4/2021	1.7	Not Required	Not Required	1.7	Yes	6/4/2021	Not Applicable
2021- TZES- 084	Tappan Zee ES	1	Classroom 402 (BOCES Main Office) Sink Fountain	6/4/2021	1.7	Not Required	Not Required	1.7	Yes	6/4/2021	Not Applicable
2021- TZES- 085	Tappan Zee ES	1	Classroom 402 (BOCES Main Office) Bathroom Sink Fountain	6/4/2021	<1.0	Not Required	Not Required	<1.0	Yes	6/4/2021	Not Applicable

Non-Applicable Outlets Below (these are outlets that were determined by the District to not be used for cooking or drinking by staff or students.)

2021- TZES- 088	Tappan Zee ES	1	Outside of Girls Bathroom by Room 205 <i>Tempered</i> Sink (right when facing) Faucet #2	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	Outlet classified as "non applicable". DO NOT DRINK signage displayed; ongoing education provided to staff and students to not consume water from this type of outlet.
2021- TZES- 089	Tappan Zee ES	Exterior	Exterior Hose Bib #1	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	Outlet classified as "non applicable". Special tool needed to access; ongoing education provided to staff and students to not consume water from this type of outlet.
2021- TZES- 090	Tappan Zee ES	Exterior	Exterior Hose Bib #2	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	Outlet classified as "non applicable". Special tool needed to access; ongoing education provided to staff and students to not consume water from this type of outlet.
2021- TZES- 091	Tappan Zee ES	Exterior	Exterior Hose Bib #3	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	Outlet classified as "non applicable". Special tool needed to access; ongoing education provided to staff and students to not consume water from this type of outlet.
2021- TZES- 092	Tappan Zee ES	Exterior	Exterior Hose Bib #4	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	Outlet classified as "non applicable". Special tool needed to access; ongoing education provided to staff and students to not consume water from this type of outlet.
2021- TZES- 093	Tappan Zee ES	Exterior	Exterior Hose Bib #5	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	Outlet classified as "non applicable". Special tool needed to access; ongoing education provided to staff and students to not consume water from this type of outlet.
2021- TZES- 094	Tappan Zee ES	Exterior	Exterior Hose Bib #6	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	<i>Not Sampled</i>	Outlet classified as "non applicable". Special tool needed to access; ongoing education provided to staff and students to not consume water from this type of outlet.