

Sample Number	School	Floor	Location/Classroom #	First Sample Date	First Sample Results (in parts per billion)	Remediation Action -- Required for any outlet > 5.0 parts per billion	Resampling Dates -- Required After Remediation Action	Passing/Clearance Results (in parts per billion; must be ≤ 5.0 parts per billion)	Is Outlet in Compliance?	Passing/Clearance Date	Reason why Outlet was NOT Sampled & Actions Taken to Prevent Consumption
2021-SO-HS-001	Tappan Zee High School	1	Library Office Sink Faucet	5/26/21	3.1	Not Required	Not Required	3.1	Yes	5/26/21	Not Applicable
2021-SO-HS-002	Tappan Zee High School	1	300's Wing Hallway - Water Cooler Fountain (Combo Unit) - Mouth	5/26/21	<1.0	Not Required	Not Required	<1.0	Yes	5/26/21	Not Applicable
2021-SO-HS-003	Tappan Zee High School	1	300's Wing Hallway - Water Cooler Fountain (Combo Unit) - Bottle Filler	5/26/21	<1.0	Not Required	Not Required	<1.0	Yes	5/26/21	Not Applicable
2021-SO-HS-004	Tappan Zee High School	1	500's Wing Hallway - Water Cooler Fountain (Combo Unit) - Mouth	5/26/21	<1.0	Not Required	Not Required	<1.0	Yes	5/26/21	Not Applicable
2021-SO-HS-005	Tappan Zee High School	1	500's Wing Hallway - Water Cooler Fountain (Combo Unit) - Bottle Filler	5/26/21	<1.0	Not Required	Not Required	<1.0	Yes	5/26/21	Not Applicable
2021-SO-HS-006	Tappan Zee High School	1	400's Wing Hallway - Water Cooler Fountain (Combo Unit) - Mouth	5/26/21	<1.0	Not Required	Not Required	<1.0	Yes	5/26/21	Not Applicable
2021-SO-HS-007	Tappan Zee High School	1	400's Wing Hallway - Water Cooler Fountain (Combo Unit) - Bottle Filler	5/26/21	<1.0	Not Required	Not Required	<1.0	Yes	5/26/21	Not Applicable
2021-SO-HS-008	Tappan Zee High School	1	Room 422 Classroom Sink Faucet	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021-SO-HS-009	Tappan Zee High School	1	Nurse's Office Water Cooler Fountain	5/26/21	9.4	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021-SO-HS-010	Tappan Zee High School	1	Nurse's Office Main Room Sink Faucet	5/26/21	4	Not Required	Not Required	4	Yes	5/26/21	Not Applicable
2021-SO-HS-011	Tappan Zee High School	1	Nurse's Office Recovery Room (with Curtain) Sink Faucet	5/26/21	11.9	Do Not Drink Sign installed, new aerator installed, to be resampled.	TBD	Pending	No	Pending	Not Applicable
2021-SO-HS-012	Tappan Zee High School	1	Nurse's Office Recovery Room (without Curtain) Sink Faucet	5/26/21	2380.0	Do Not Drink Sign installed, filter was installed, to be resampled.	TBD	Pending	No	Pending	Not Applicable
2021-SO-HS-013	Tappan Zee High School	1	Main Office Hallway (across from SRO office) Water Cooler Fountain Upper	5/26/21	11.4	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021-SO-HS-014	Tappan Zee High School	1	Main Office Hallway (across from SRO office) Water Cooler Fountain Lower	5/26/21	12.4	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021-SO-HS-015	Tappan Zee High School	1	Room 701 (Assistant Principal's Office) Sink Faucet	5/26/21	16.3	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021-SO-HS-016	Tappan Zee High School	1	Classroom 705A Faucet	5/26/21	1.6	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021-SO-HS-017	Tappan Zee High School	1	Classroom 705 Faucet	5/26/21	1.4	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021-SO-HS-018	Tappan Zee High School	1	500's Wing Hallway Water Cooler Fountain (next to Staff Women's Bathroom)	5/26/21	4.1	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021-SO-HS-019	Tappan Zee High School	1	1ST Floor C-13 - School Store Kitchen Faucet	5/26/21	<1.0	Not Required	Not Required	<1.0	Yes	5/26/21	Not Applicable
2021-SO-HS-020	Tappan Zee High School	1	Classroom 950 (Facility Room) Sink Faucet	5/26/21	1.8	Not Required	Not Required	1.8	Yes	5/26/21	Not Applicable
2021-SO-HS-021	Tappan Zee High School	1	Classroom 951 (Music Room) Sink Faucet (Left When Facing)	5/26/21	348.0	Outlet permanently removed from service.	6/22/21	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service	Outlet Permanently Removed from Service
2021-SO-HS-022	Tappan Zee High School	1	Classroom 951 (Music Room) Sink Faucet 2 (Right When Facing)	5/26/21	2.4	Not Required	Not Required	2.4	Yes	5/26/21	Not Applicable
2021-SO-HS-023	Tappan Zee High School	1	VOID	VOID	VOID	VOID	VOID	VOID	VOID	VOID	Not Applicable
2021-SO-HS-024	Tappan Zee High School	1	Auditorium Hallway - Water Cooler Fountain (Combo Unit) - Mouth	5/26/21	<1.0	Not Required	Not Required	<1.0	Yes	5/26/21	Not Applicable
2021-SO-HS-025	Tappan Zee High School	1	Auditorium Hallway - Water Cooler Fountain (Combo Unit) - Bottle Filler	5/26/21	<1.0	Not Required	Not Required	<1.0	Yes	5/26/21	Not Applicable
2021-SO-HS-026	Tappan Zee High School	1	Auditorium Hallway - Water Cooler Single Fountain	5/26/21	<1.0	Not Required	Not Required	<1.0	Yes	5/26/21	Not Applicable
2021-SO-HS-027	Tappan Zee High School	1	Kitchen Prep Double Sink Faucet 1 (By Refrigerator Wall - Left When Facing)	5/26/21	1.3	Not Required	Not Required	1.3	Yes	5/26/21	Not Applicable
2021-SO-HS-028	Tappan Zee High School	1	Kitchen Prep Double Sink Faucet 2 (By Refrigerator Wall - Right When Facing)	5/26/21	2.4	Not Required	Not Required	2.4	Yes	5/26/21	Not Applicable
2021-SO-HS-029	Tappan Zee High School	1	Kitchen Single Hand Washing (White) Sink Faucet	5/26/21	3.4	Not Required	Not Required	3.4	Yes	5/26/21	Not Applicable
2021-SO-HS-030	Tappan Zee High School	1	Kitchen Single Sink Faucet (By Window Wall)	5/26/21	2.8	Not Required	Not Required	2.8	Yes	5/26/21	Not Applicable
2021-SO-HS-031	Tappan Zee High School	1	Kitchen Double Sink (By Window Wall & Detergent Dispensers) Faucet 1 (Left When Facing)	5/26/21	8.4	Do Not Drink Water sign installed, filter to be installed then resampled.	TBD	Pending	No	Pending	Not Applicable
2021-SO-HS-032	Tappan Zee High School	1	Kitchen Double Sink (By Window Wall & Detergent Dispensers) Faucet 2 (Right When Facing)	5/26/21	1.5	Not Required	Not Required	1.5	Yes	5/26/21	Not Applicable
2021-SO-HS-033	Tappan Zee High School	1	Kitchen Ice Machine	6/22/21	Pending	Out of Order Sign Placed on Unit, Filter to be installed then resampled.	Pending	Pending	No	Pending	Not Applicable



















2021-SO-HS-297	Tappan Zee High School	L	100's Wing - Records/BACES Room- Bathroom Sink Tempared Faucet	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - NOT DRINK signage displayed, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-298	Tappan Zee High School	1	All Eyewash Stations in the School	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - NOT DRINK signage displayed, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-299	Tappan Zee High School	Exterior	Fieldhouse/Trackbar (By Football Field) Men's Bathroom Sink Faucet 1 (left when facing)	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Applicable
2021-SO-HS-300	Tappan Zee High School	Exterior	Fieldhouse/Trackbar (By Football Field) Men's Bathroom Sink Faucet 2 (right when facing)	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Applicable
2021-SO-HS-301	Tappan Zee High School	Exterior	Fieldhouse/Trackbar (By Football Field) Women's Bathroom Sink Faucet 1 (left when facing)	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Applicable
2021-SO-HS-302	Tappan Zee High School	Exterior	Fieldhouse/Trackbar (By Football Field) Women's Bathroom Sink Faucet 2 (right when facing)	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Applicable
2021-SO-HS-303	Tappan Zee High School	Exterior	Outside Room 419- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-304	Tappan Zee High School	Exterior	Outside Room 411- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-305	Tappan Zee High School	Exterior	Outside Room 401- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-306	Tappan Zee High School	Exterior	Outside Room 607- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-307	Tappan Zee High School	Exterior	Outside Room Auditorium Entrance- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-308	Tappan Zee High School	Exterior	West Wall Outside by Stage- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-309	Tappan Zee High School	Exterior	Outside Loading Dock by Stairs- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-310	Tappan Zee High School	Exterior	Directly Outside Kitchen - South Wall -Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-311	Tappan Zee High School	Exterior	Outside Kitchen West- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-312	Tappan Zee High School	Exterior	Outside Kitchen East- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-313	Tappan Zee High School	Exterior	In Courtyard by Teacher's Lounge- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-314	Tappan Zee High School	Exterior	In Courtyard by Cafeteria East- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-315	Tappan Zee High School	Exterior	Outside Room Boys/Locker Room- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
2021-SO-HS-316	Tappan Zee High School	Exterior	Outside Courtyard by Library- Exterior Hose Bib	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Not Sampled	Water temperature not applicable - Special tool needed to access, ongoing education provided to staff and students to not consume water from this type of water tap/faucet - not applicable
This spreadsheet was last updated on 7-27-21												